

Index of Government Exhibits

1. Pelican Refining, LLC Sign – 4646 Old Town Rd., Lake Charles, LA 20615. (Source: EPA-CID)	14. Process Flare Stack. (Source: LDEQ)
2. Pelican Refining, LLC Gate and Asphalt Loading Entrance. (Source: EPA-CID)	15. Flare Gun. (Source: EPA-CID)
3. Pelican Refining, LLC Satellite Photo. (Source: Google website)	16. Flare Circular Chart. (Source: EPA-CID)
4. Pelican Refining, LLC Aerial Photo. (Source: Louisiana State Police)	17. Hydrogen Sulfide monitors. (Source: EPA-CID)
5. View of Lake Charles facility from Calcasieu River. (Source: EPA-CID)	18. Asphalt Laboratory. (Source: EPA-CID)
6. Schematic of Pelican Lake Charles Facility. (Source: EPA-CID)	19. Asphalt Laboratory. (Source: EPA-CID)
7. Petroleum Storage Tanks. (Source: Louisiana State Police)	20. Refinery Control Room. (Source: EPA-CID)
8. Oil spill in containment between Tank 110-16 and Tank 30-40. (Source: LDEQ)	21. Vacuum Distillation Tower. (Source: LDEQ)
9. Tank 110-16 with sunken roof. Oil observed on top of roof.	
10. Tank 110-16 with sunken roof. Source: LDEQ)	
11. Oil spill in containment by Tank 55-18. (Source: LDEQ)	
12. Photos from 03/01/06 LDEQ Inspection. (Source: LDEQ)	
13. Photos from 3/1/06 LDEQ Inspection. (Source: LDEQ)	

Exhibit 1. Pelican Refining, LLC Sign – 4646 Old Town Rd., Lake Charles, LA 20615.



Exhibit 2. Pelican Refining, LLC Gate and Asphalt Loading Entrance.



Exhibit 3. Pelican Refining, LLC Satellite Photo.



Exhibit 4. Pelican Refining, LLC Aerial Photo.



Exhibit 5. View of Lake Charles facility from Calcasieu River.





Exhibit 6. Schematic of Pelican Lake Charles Facility.

CALIBRATION
BY _____ DATE _____
CALIBRATION
CARTON INC. 3-800-231-5588 STOCK NO. 100

CALIBRATION
BY _____ DATE _____
CALIBRATION
CARTON INC. 3-800-231-5588 STOCK NO. 100

CALIBRATION
BY _____ DATE _____
CALIBRATION
CARTON INC. 3-800-231-5588 STOCK NO. 100



TANK

SAFE

10.08.2007 11:29

Exhibit 7. Petroleum Storage Tanks.



Exhibit 8. Oil Spill in containment between Tank 110-16 and Tank 30-04.



Exhibit 9. Tank 110-16 with sunken roof. Oil observed on top of roof.



Exhibit 10. Tank 110-16 with sunken roof.



Exhibit 11. Oil spill in containment by Tank 55-18.



Exhibit 12. Photos from 3/1/06 LDEQ Inspection.





Exhibit 13. Photos from 3/1/06 LDEQ Inspection.

Exhibit 14. Process Flare Stack.



Exhibit 15. Flare Gun.



Exhibit 16. Flare Circular Chart.



Exhibit 17. Hydrogen Sulfide monitors.



Exhibit 18. Asphalt Laboratory.



Exhibit 19. Asphalt Laboratory.



Exhibit 20. Refinery Control Room.



Exhibit 21. Vacuum
Distillation Tower.

